MATERIAL SAFETY DATA SHEET

FOR COATINGS, RESINS AND RELATED MATERIALS

DMS	QPL	1824	Ì
איוע			

DATE OF PREP.

August 1977

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20)

Section I

MANUFACTURER'S NAME

Koppers Company, Inc.

STREET ADDRESS 5431 District Blvd.

CITY, STATE, AND ZIP CODE

Vernon, CA 90040

EMERGENCY TELEPHONE NO.

213 - 726-8666

PRODUCT CLASS

Vinyl Texture

MANUFACTURERS CODE IDENTIFICATION

L-770-66

#430 Hansa Yellow

TRADE NAME

Section II — HAZARDOUS INGREDIENTS							
INGREDIENT	PERCENT	PPM	LV mg/M³	LEL	VAPOR PRESSURE		
Methyl Ethyl Ketone Propylene Oxide Isophorone SO-1200 Solvent N-Butanol Methyl Ethyl Ketone Cellosolve Solvent N-Butyl Acetate Vinyl Chloride Vinyl Acetate Trepolymer	57.78 .12 .23 5.71 1.51 3.89 1.35 .73 18.20	200 100 25 150 100 100 200 150	590 240 141 - 303 409 740 710 15	1.8 2.1 .8 1.2 1.4 1.3 2.6 1.7	71,2mm/20°C 400mm/17.8°C 1mm/38°C 36mm/100°F 5.5mm/20°C 16mm/20°C 3.8mm/20°C 15mm/25°C		

Section	. []]	DLIV	CICAI	DATA

BOILING RANGE

175-244°F

VAPOR DENSITY

HEAVIER

LIGHTER, THAN AIR

EVAPORATION RATE

FASTER

SLOWER. THAN ETHER

PERCENT VOLATILE BY VOLUME 80%

GALLON

Section IV — FIRE AND EXPLOSION HAZARD DATA

DOT CATEGORY

Flammable - Red Label

FLASH POINT 23°F TCC

LEL 1.0

EXTINGUISHING MEDIA

Carbon dioxide, dry chemical or foam

UNUSUAL FIRE AND EXPLOSION HAZARDS

May form explosive vapor mixture between upper and lower explosive limits. Do not use welding or cutting torch near or on the drum (even empty).

SPECIAL FIRE FIGHTING PROCEDURES

Do not use water

Section V — HEALTH HAZARD DATA					
THRESHOLD LIMIT VALUE N/A EFFECTS OF OVEREXPOSURE Headache, nausea, moderately irritating to eyes and skin					
EMERGENCY AND FIRST AID PROCEDURES Remove victims from vapors - restore breathing if necessary. Remove from skin with soap and water.					
Flush eyes with water.					
Section VI — REACTIVITY DATA					
STABILITY UNSTABLE X STABLE CONDITIONS TO AVOID INCOMPATABILITY (Materials to avoid) HAZARDOUS DECOMPOSITION PRODUCTS CO, CO2, aldehydes, hydrogen chloride, and other organics					
HAZARDOUS POLYMERIZATION MAY OCCUR will not occur conditions to avoid					
Section VII — SPILL OR LEAK PROCEDURES					
Remove sources of ignition. Apply sawdust or other absorbent material. Keep material from spreading. WASTE DISPOSAL METHOD Put in metal container and seal for disposal.					
Section VIII — SPECIAL PROTECTION INFORMATION					
For confined aread use Bureau of Mines Respiratory Device Approval 25 B-13 BM2304 Face Piece BM2304 Cartridge BM2313 Filters BM2313 Filter Clips					
Ventilation should be adequate to keep lower level below LEL					
PROTECTIVE GLOVES Rubber EYE PROTECTION Safety OTHER PROTECTIVE EQUIPMENT Rubber soles must be worn (no static electricity)					
Section IX — SPECIAL PRECAUTIONS					
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING					
Flammable - store away from open flame and high heat.					
OTHER PRECAUTIONS Do not take internally - avoid prolonged contact with skin.					